

**DATE:** AUGUST 1, 1997  
**MODEL YEAR:** 1992 - 1997  
**CHASSIS MODEL:** UD1300/UD1400  
**ENGINE MODEL:** TD42T/TD42TI  
**BULLETIN #:** EC - 05  
**FILE IN THE ENGINE SECTION OF THE TECHNICAL BULLETIN BINDER**

**TD42T / TD42TI THERMOSTAT HOUSING CHANGE**

**CHANGE NOTICE:**

The thermostat housing for the TD42T and TD42TI engines has been changed to further improve its durability. The new thermostat housing has an Alumite surface treatment on the inside.

**PARTS NOTICE:**

The new thermostat housing can be substituted to perform the function of the former part numbers according to the chart below.

PART NAME	PART NUMBER	
	FORMER	NEW
THERMOSTAT HOUSING	11061 - 30J00 11061 - 30J01	11061 - 09D60

